



NFTAC

NATIONAL FIREBIRD and TRANS AM CLUB

TECHNICAL SECTIONS Volume II

Reprints from the 1998 thru 2007 NFTAC *EAGLE*

AVAILABLE IN CD AND PRINTED FORMATS

Volume I covering earlier publications and Volume III covering later publications
also available from the NFTAC

PUBLISHED BY THE NFTAC

5433 N. ASHLAND AVE., CHICAGO, IL 60640 U.S.A.

phone/text: 773-769-7166

fax: 773-769-3240

email: info@firebirdtaclub.com

web site: firebirdtaclub.com or www.firebirdclub.net

NFTAC TECHNICAL SECTIONS VOLUME II

<u>PUBLICATION</u>	<u>PAGE</u>
1998 February	10
1998 August	15
1998 November	23
1999 February	25
1999 May	30
1999 November	39
2000 February	43
2000 May	49
2000 August	55
2000 November	60
2001 February	63
2001 May	67
2001 August	70
2001 November	73
2002 February	78
2002 May	83
2002 August	88
2002 November	93
2003 February	97
2003 May	100
2003 August	107
2004 January	114
2004 May	119
2004 August	123
2004 November	130
2005 February	134
2005 May	138
2005 August	142
2006 January	144
2006 May	146
2006 August	148
2006 November	150
2007 February	154
2007 May	158
2007 August	160

NOTE: Please note the ads that may appear here are reproduced as they originally appeared in that issue and therefore may be several years old and are not to be relied on for prices or information.

Nothing may be reproduced in whole or in part without the express written consent of the publisher. The views of contributing writers are their own and not necessarily the views of the NFTAC. Readers are warned in following any advice given and no liability either express or implied is assumed by the advice or opinions given by individual contributors or the NFTAC.

Copyright © 2017, NFTAC

ARTICLE INDEX

Publication references in which NFTAC publication the article originally appeared and the year; the page number it was on and if a Question and Answer (Q & A), its position on the page and page number in this issue.

SUBJECT/ ARTICLE	ORIGINAL PUBLICATION ISSUE	PAGE	Q & A	PAGE NUMBER THIS ISSUE
Brakes				
Adjusting rear discs	2002 November	33	3	95
Brakes shaking steering wheel	2000 May	35	1	54
Drum to disc brakes	2002 November	33	1	95
Parking brake	2002 November	29	1	97
Carburetion/Fuel System				
'72 hood air scoop	1999 May	34		35
Aftermarket ram air system	2000 August	32	3	57
Air intake tube	2004 August	32	1	126
Airflow sensor screen	2000 August	29	6	56
Black residue	2006 August	26	1	149
Carb size	2005 August	22	1	143
Cold air induction	1998 November	29	1	24
Fried fuel pump	2000 August	29	3	56
Fuel injector replacement	2001 May	32	1	68
Gasoline vapor smell	1999 May	29	3	33
Gas smell	1998 November	29	2	24
Intake manifold/scoop	2006 May	22	2	146
Ram air intake modification	2007 August	22	2	160
Stalling	2005 May	23	1	139
Stock throttle body	2001 August	32	1	70
Surging	2005 August	21	5	142
TPI Installation	2001 February	29	4	64
Tripower installation	2002 May	29	4	84
Wrong gas	2000 November	32	3	61
Cooling and Heating Systems				
'79 carb fit	2000 May	29	2	50
AC recharging	2003 August	29	5	110
AC removal	2001 November	28	2	73
Cracked heater core	2005 May	23	3	139
Downshift control cable	2001 November	28	3	73
Cooling fans	2005 August	21	4	142
Heater blower	2002 February	32	4	80
Heater core leakage	2003 February	32	1	98
Heater core replacement	2000 May	28	2	49
Heater core removal	2002 February	28	1	78
Low pressure AC port	2002 February	29	2	79

SUBJECT/ ARTICLE	ORIGINAL PUBLICATION		PAGE NUMBER	
	ISSUE	PAGE	Q & A	THIS ISSUE
Overheating	1999 November	25	6	39
Overheating	2001 February	32		65
Overheats	1999 November	25	4	39
Radiator hose collapse	2004 November	26	1	133
Running hot	2000 November	29	2	60
Running hot with AC on	2004 January	34		118
Temperature sending unit	2003 August	33	4	112
Water temperature	2000 August	29	2	56
Windshield defroster	2003 August	29	1	110
Electrical				
'06 & '97 headlight doors	2000 August	33		58
2nd gear start switch	2000 May	28	1	49
32 amp alternator installation	2003 May	32	1	104
4th generation headlight fix	2002 May	33		86
'88 digital dash	2003 May	28	6	102
Another headlight fix	2002 May	34		92
Computer checks	1998 August	29	2	19
ESM reset	2000 February	29		46
Electrical system transfer	1999 May	32	2	34
Firing order	2002 February	32	3	80
Headlight door noise	2002 November	34		96
Headlights	1999 February	34		28
Headlights to stay open	1999 November	25	1	39
Hidden headlight repair	2000 May	33		52
Horn relay	2004 May	33	4	121
Instrument lights	2002 November	28	1	93
Left headlight not opening	2001 August	34	4	72
Low track light	2000 November	32	7	61
Radio codes	2003 May	33		105
Radio head unit	2004 August	26	2	123
Radio problem	2003 May	27	4	101
Rear lights	2004 January	28	5	115
Service engine light	2001 February	28	3	63
SES light	2005 May	23	4	139
Stock headlights on 3rd gen	2004 January	34		118
Turn signal bulb	2002 February	28	4	78
Emission Controls				
California smog equipment	1999 February	32	1	26
Fault codes	1998 August	29	1	19
Red catalytic converter	2002 February	28	3	78

SUBJECT/ ARTICLE	ORIGINAL PUBLICATION		PAGE NUMBER	
	ISSUE	PAGE	Q & A	THIS ISSUE
Engine/Mechanical				
4th generation headlight fix	1999 November	26		40
403 Olds modifications	2007 February	21	1	154
350 & 400 engine difference	2002 May	29	3	84
'67 original engine	2000 May	28	5	49
'80 Trans Am with 400	2001 February	29	5	64
'81 TA engines	2000 August	29	5	56
Belt replacement	1999 February	33	2	27
Belt squealing	2005 February	22	4	134
Bigger engine	2001 May	29	3	67
Boring out	2002 February	32	1	80
Cadillac engine	2007 February	22	2	155
Engine hoist	1999 May	32	1	34
Engine removal	2002 February	28	2	78
Engine replacement	2002 May	34		92
Engine seal replacement	2000 May	32	1	51
Engine setup	1998 February	28	2	10
Engine swap	1999 November	25	7	39
Engine swap #2	2001 May	29	4	67
Check engine light	2000 August	32	4	57
Check engine light pt. 2	2001 May	29		67
Horsepower buildup	2002 February	32	2	80
Horsepower ratings	2000 February	26	4	43
Idle stall	2000 November	32	1	61
Insulating manifold heat	2004 November	23	2	131
Manifold insulation	1999 February	33	1	27
More horsepower	2000 May	28	3	49
Motor mounts for 400	2002 May	29	5	84
Not starting	2007 May	22	2	158
Olds 403 power	2001 May	32	3	68
Olds 403 specs	2004 August	27	1	124
Olds engine	1999 November	25	5	39
Peak performance	2001 May	32	2	68
Power steering fluid	2003 August	27	4	108
Ram air V engine	2000 August	33		58
Rattling noise	2000 February	27	3	44
RPM surge	2001 August	33	2	71
Running rough	2001 February	28	1	63
Supercharger	2002 November	32	4	94
Starting problems	2001 February	29	1	64
Vortec supercharger	2000 November	33		62
Ticking sound	1999 May	29	2	33

SUBJECT/ ARTICLE	ORIGINAL PUBLICATION		PAGE NUMBER	
	ISSUE	PAGE	Q & A	THIS ISSUE
Exhaust				
Aftermarket headers	1999 February	35	1	29
Best Cat-Back exhaust	2002 February	29	3	79
Dual exhaust	2003 February	32	2	98
Edelbrock manifold	2004 January	27	5	114
Edelbrock performer	2001 August	32	4	70
Exhaust manifold bolts	2002 November	32	2	94
Exhaust replacement	2003 August	34		113
Exhaust system replacement	2004 May	28	4	119
Flowmaster	2004 January	33	2	117
Flowmaster exhaust	2002 August	28	3	88
Headers	2002 February	33		81
Headers for a 301	2004 May	28	1	119
Manifolds	2006 August	26	3	149
Muscle car sound	2005 August	21	2	142
Ram Air III exhaust	2001 February	29	2	64
Exterior/Body				
400 hood	2006 May	22	1	146
'78 Formula t-tops	2000 February	27	1	44
'79 decal set	2000 August	32	2	57
'92 model year paint	2000 August	29	1	56
American hatch t-tops	2006 November	21	3	150
Bumper emblem	2000 February	26	1	43
Eagle decal	2005 May	25	1	140
Fiberglass fenders	2005 May	22	1	138
Ground effects	2007 May	22	1	158
GTA emblem	2007 February	26	3	156
Precut striping	2000 May	29	1	50
Rear quarter replacement	2000 November	32	4	61
Rear spoiler replacement	2005 August	22	2	143
Shaker hood scoops	2000 November	29	1	60
Spoilers cracking	2001 May	29	1	67
T-top crack	2002 February	29	4	79
T-top seals	2000 August	28	3	55
Weather-stripping	2002 February	29	1	79
Gauges				
Autometer gauges	2005 February	22	1	134
Gauge Dial repair	1999 November	25	5	39
Generator light	2002 May	32	4	85

SUBJECT/ ARTICLE	ORIGINAL PUBLICATION		Q & A	PAGE NUMBER
	ISSUE	PAGE		THIS ISSUE
General				
14 second car	2001 August	34	1	72
5 Questions	1999 February	29	4	25
'70 1/2 value	2000 February	26	3	43
'78 Redbird	2003 May	26	1	100
'80 pace car	2002 February	32	5	80
'99 Firehawk	2000 November	33	1	62
Acceleration increase	2001 August	34	5	72
Bat out of hell	2001 November	28	1	73
Car storage	1998 February	33		12
Differences in '70 to '73 TAs	1998 August	32		20
F in F-body	2000 August	33		58
First TA production date	2003 May	28	1	102
Make '93 faster	2000 February	26	2	43
NASCAR stickers	2005 February	26	4	136
Performance chips	2000 August	33		58
Performance hints	2002 February	33		81
Performance testing	1999 February	32	2	26
Power steering leak	2002 February	29	5	79
Power to '75 Trans Am	2006 August	22	1	148
Power to wheels	2006 January	22	1	144
Research history of car	2005 February	23		135
Restoration	1998 February	28	1	10
Rocket boost	2003 May	33		105
Rollover ratings	2000 February	28		45
Service manual	2002 May	28	2	83
Setting timing	2001 November	29		74
Stated Value Insurance	1998 August	16		15
Trans Am from Firebird	2005 August	21	1	142
Turbo S.E. difference	2002 May	29	1	84
Windshield washer	2002 February	33		81
Winter storage tips	2001 November	29		74
Windshield washer	2002 February	34		82
Y-82 meaning	2007 August	22	1	160
Interior				
Back window removal	2005 May	23	2	139
Bucket seat replacement	2002 May	28	1	83
Console replacement	2007 February	29	2	157
Cracked dash fixing	2002 November	34		96
Door alignment	2004 May	34		122
Headliner removal	2003 August	33	1	112
Hinges	2005 February	22	2	134
Interior upgrade	2002 November	34		96

SUBJECT/ ARTICLE	ORIGINAL PUBLICATION		PAGE NUMBER	
	ISSUE	PAGE	Q & A	THIS ISSUE
Loose windows	1999 November	25	2	39
Parchment seat covers	2005 May	23	5	139
Part Changeability	2001 February	28	2	63
Rear deck replacement	2005 February	26	2	136
Seat belt guide removal	2002 May	29	2	84
Seat color	2006 November	22	1	151
Seat covers	2006 November	21	1	150
Steering wheel emblem	2006 November	26	1	152
Steering wheel removal	2002 February	34		82
Trunk release	2004 August	26	1	123
Window relay	1998 November	28	2	23
Numbers/Identification				
Decode 4th generation VIN	1998 February	25		14
GM Vin Digit Identification	2000 May	35		54
Vin Number Breakdown	1999 November	28		42
Vin Number Breakdown pt. 2	2000 February	32		47
Oil/Lubrication				
The Dirt on oil	1999 May	24		30
Oil changes	2004 August	26	3	123
Oil type	2001 August	33	1	71
Posi oil	2005 August	22	3	143
Synthetic oils	2006 August	26	2	149
Suspension/Handling				
Coil spring replacement	2000 February	27	2	44
Limited slip additive	1999 May	29	1	33
Lowering a 2nd generation	2004 May	34		122
Rack and pinion	2001 August	32	2	70
Shocks	2007 February	26	1	156
Spring spacers	2006 November	21	2	150
Suspension improvements	2005 August	21	3	142
Stock Auburn gear	2001 August	32	3	70
Thunking noise	2001 May	29	2	67
Vibration	2002 May	28	5	83
Vibration on 4th generation	2000 November	33		62
Vibration problem	2002 May	34		92
WS-6 first year	2000 August	32	1	57
WS-6 package	2001 August	32	5	70
WS-7 handling package	2003 August	34		113
WS-7 suspension	2002 May	28	3	83
Tires/Wheels				

SUBJECT/ ARTICLE	ORIGINAL PUBLICATION		PAGE NUMBER	
	ISSUE	PAGE	Q & A	THIS ISSUE
'70 TA wheel sizes	2002 May	29	7	84
8 inch rims	2003 May	28	5	102
'92 wheels	2001 February	33	1	66
Center caps	2002 November	32	1	94
Long shank lug nuts	1998 November	28	1	23
Restoring wheels	1998 February	35		14
Refinish rims	2002 May	33	2	91
Restoring wheels	004 August	34		128
Tire rotation	2000 May	33		52
Tire replacement	2000 August	28	1	55
Tire size	2004 August	34		128
Tires	1999 February	34		28
Tires pt. 2	2004 November	27		133
Transmission/Clutch/Drive Train				
4.10 rear end	2002 May	32	2	90
700R4 transmission	2000 November	32	5	61
Clunking noise	2000 May	28	5	49
Clutch replacement	2000 November	33	2	62
Gears	2006 May	26	1	147
Hurst usage	2001 August	33	3	71
Powerglide transmission	2007 February	21	2	154
Transmission choice	2002 February	33		81
Transmission leakage	2006 August	22	2	148
Transmission service	2000 May	33		52
Transmission swap	2001 May	33		69
Transmission tuning	1998 August	28	1	18
Transmission tuning pt. 2	2004 August	33	1	127



NATIONAL FIREBIRD and TRANS AM CLUB

TECHNICAL SECTIONS Volume III

Reprints from the 2008 thru 2017 NFTAC *EAGLE*

AVAILABLE IN CD AND PRINTED FORMATS

Volume I and Volume II covering publications also available from the NFTAC

PUBLISHED BY THE NFTAC
5433 N. ASHLAND AVE., CHICAGO, IL 60640 U.S.A.
Phone: 773-769-7166
FAX: 773-769-3240
email: info@firebirdtaclub.com
web site: firebirdtaclub.com or www.firebirdclub.net

NFTAC TECHNICAL SECTIONS VOLUME III

<u>PUBLICATION</u>	<u>PAGE</u>
2008 January	13
2008 May	16
2008 August	18
2008 November	21
2009 February	24
2009 May	27
2009 August	27
2010 January	35
2010 May	38
2010 August	41
2010 November	44
2011 February	47
2011 May	49
2011 August	52
2011 November	54
2012 February	56
2012 May	59
2012 August	62
2012 November	64
2013 February	66
2013 May	68
2013 August	70
2013 November	73
2014 February	76
2014 May	74
2014 August	80
2014 November	82
2015 February	84
2015 May	86
2015 August	88
2015 November	90
2016 February	92
2016 May	90
2016 August	96
2016 November	98
2017 February	100
2017 May	102
NFTAC Store Order Form	104
NFTAC Membership Application	105

NOTE: Please note the ads that may appear here are reproduced as they originally appeared in that issue and therefore may be several years old and are not to be relied on for prices or information.

Nothing may be reproduced in whole or in part without the express written consent of the publisher. The views of contributing writers are their own and not necessarily the views of the NFTAC. Readers are warned in following any advice given and no liability either express or implied is assumed by the advice or opinions given by individual contributors or the NFTAC.

ARTICLE INDEX

Publication references in which NFTAC publication the article originally appeared and the year; the page number it was on and if a Question and Answer (Q & A), its position on the page and page number in this issue.

SUBJECT/ <u>ARTICLE</u>	ORIGINAL PUBLICATION		PAGE NUMBER	
	<u>ISSUE</u>	<u>PAGE</u>	<u>Q & A</u>	<u>THIS ISSUE</u>
Brakes				
Brakes pulsing	2016 May	23	1	94
Caliper sizes	2008 August	21	3	18
Disc brake conversion	2009 February	26	2	25
Rear brakes not working	2016 August	24	1	96
Rear drum to disc conversion	2015 August	26		89
Carburetion/Fuel System				
305 to 350 carburetor	2014 February	26	1	77
Car shutting off	2013 May	26	2	68
Carb problems	2009 May	26	4	33
Carb size	2011 November	23	3	54
Carburetor throttle	2008 November	26	2	22
Carburetor troubleshooting	2010 January	27	1	37
Edelbrock carb	2009 August	21	1	31
Edelbrock performer package	2014 November	26	1	83
Fuel pump and no gas	2012 February	23	2	56
Fuel pump problems	2013 August	23	2	70
Fuel pump relay	2016 November	24	2	98
Fuel pump relay	2016 November	25	1	99
Gas incorrect	2013 August	26	3	71
No throttle response	2009 May	26	2	29
T.P. I. throttle	2013 November	26	4	74
Cooling/Heating Systems				
A/C evaporate condensate line	2010 January	26	2	36
A/C and heat duct pipes	2015 May	26	4	87
Coolant flow sensor	2012 May	26	5	60
Coolant hose leak	2010 November	26	1	45
Coolant lights	2012 May	26	4	60
Heater control vacuum	2009 August	26	2	33
Heater core replacement	2011 February	22	1	47
Heater core replacing	2011 November	22	2	54
Heater not working	2014 May	26	3	79
Overheating	2013 November	27		75

SUBJECT/ <u>ARTICLE</u>	ORIGINAL PUBLICATION		PAGE NUMBER	
	<u>ISSUE</u>	<u>PAGE</u>	<u>Q & A</u>	<u>THIS ISSUE</u>
Overheating caused by fan	2016 August	25	1	97
Electrical				
Battery runs down	2008 August	21	4	18
Blinkers not working	2015 August	23	2	88
Chip question	2017 February	24	4	100
Computer out	2013 August	26	1	71
Delco alternator number	2017 May	25	2	102
Electric schematic diagram	2008 May	21	1	16
Electrical problems	2008 November	27	1	22
Exterior lights	2010 November	23	1	44
Fan switch	2013 May	26	3	68
Fuse box power	2010 August	26	3	42
HID headlight installation	2012 May	26	1	60
Not starting	2015 August	23	1	88
Vats system	2016 November	24	3	98
Wiring harness swap	2010 August	23	3	41
Wiring harness source	2012 May	23	1	59
Wiring harness swap	2010 August	23	3	41
Emission Controls				
EGR flow code	2012 August	26	2	62
Emission conversion	2012 August	26	3	62
Filler cap tightness	2012 May	26	2	60
Mass airflow sensor	2010 August	23	1	41
Mass airflow sensor code	2010 November	26	6	45
Mass airflow sensor removal	2012 February	26	3	57
Mass airflow sensor replacement	2014 August	23	2	80
Oxygen sensor	2012 February	26	6	57
Oxygen sensor code	2012 August	26	1	62
Engine/Mechanical				
'81 T/A engines	2012 February	26	2	57
400 version in '78 Formula	2011 May	27	1	51
403 rebuild	2015 February	26	3	85
Belt noises	2009 February	26	1	25
Block and head castings	2016 February	23	2	92
Block value	2011 February	22	2	47
Car not starting	2013 November	26	2	74

SUBJECT/ ARTICLE	ORIGINAL PUBLICATION		PAGE NUMBER	
	ISSUE	PAGE	Q & A	THIS ISSUE
Check engine light	2010 May	26	1	39
Compression	2013 May	26	1	68
Cruise control operational	2010 January	27	2	37
Engine block seal	2011 November	23	4	55
Engine knock	2015 May	26	1	87
Engine surge	2015 February	26	1	85
Engine swap in '83 Firebird	2014 February	23	3	76
Engine will not start	2013 February	26	1	66
Gasket set	2017 May	25	3	102
High torque starter	2013 May	27	2	69
Horsepower adding	2011 November	22	3	54
Horsepower increase	2015 May	23	3	86
Horsepower ratings	2011 May	23	6	50
Idle speed	2010 January	26	1	36
Ignition timing	2015 May	23	1	86
Injector replacement	2012 November	23	2	64
LT1 rebuild	2014 August	26	3	81
Misfire	2012 May	23	2	59
More power from 403	2014 February	26	4	77
Optispark distributor	2017 February	24	2	100
Original engine in '67 Firebird	2011 November	23	1	55
PCM flashing	2012 November	23	1	64
Peak performance in '78 WS6	2014 February	26	3	77
Ram air V engine	2012 February	27		58
Running rough	2013 November	23	1	73
Service engine light	2013 November	26	1	74
Starting problem	2016 November	24	1	98
Timing	2015 May	23	1	86
Timing setting	2016 February	26		93
Tuning new engine	2010 January	23	2	35
Turbo, carb, ignition	2013 August	26	2	71
Vortec heads	2014 May	26	4	79
Vortec supercharger	2013 August	27		62
WS package for 1984	2014 November	23	1	82
WS6 performance options	2012 February	26	4	57
Exhaust				
Exhaust sound	2014 August	26	2	81
Header wrap	2014 May	23	2	78

SUBJECT/ ARTICLE	ORIGINAL PUBLICATION		PAGE NUMBER	
	ISSUE	PAGE	Q & A	THIS ISSUE
Headers	2013 February	26	2	66
Headers in '87 Firebird	2014 May	26	1	79
RA III exhaust	2013 November	26	3	74
Straight pipe exhaust	2014 May	26	2	79
Exterior/Body				
'96 and '97 headlight doors	2012 February	27		57
Aero kit	2013 November	23	2	73
Bird decal adhesive	2014 May	23	3	78
Body shell	2008 January	22	1	14
Bumper emblems	2011 May	23	3	50
Car cover	2010 November	26	2	45
Convertible top/seals	2011 May	23	1	50
Doors for '98 Firebird	2016 May	26	1	95
Exterior trim colors	2009 February	22	1	24
Fender replacement	2009 May	21	1	27
Headlights flipping open	2012 February	23	1	56
Headlights manually opening	2008 May	22	3	17
Headlight height adjustment	2009 August	27	3	34
Headlight not opening	2015 May	23	2	86
Hood decal	2012 February	26	5	57
Hood scoop function	2008 May	21	2	16
Items to get great paint	2015 November	26		91
Key replacement	2008 August	21	2	18
Nose and grille swap	2008 August	26	2	20
Original color and value	2009 May	22	2	28
Original chrome shine	2010 January	23	1	35
Paint bubbles	2015 August	26		89
Paint bubbling	2014 August	23	1	80
Paint code	2013 August	23	1	70
Personal preferences	2014 May	26	7	79
Pop up headlights	2008 November	26	3	22
Primers, all about	2010 May	27		40
Primer factory colors	2010 August	27		43
Rear quarter repair	2013 August	26	4	71
Scoop seal	2009 May	27	1	30
Sequential tail lights	2013 February	27		67
Spoiler cracking	2014 February	23	1	76
Striping source	2011 November	23	2	55

SUBJECT/ ARTICLE	ORIGINAL PUBLICATION		PAGE NUMBER	
	ISSUE	PAGE	Q & A	THIS ISSUE
T-top conversion	2012 May	26	6	60
T-top type	2011 May	27	1	51
Windshield cowl rust holes	2008 November	22	3	21
Winter car wash	2011 February	27		48
WS6 markings	2017 February	25	1	101
Gauges				
Redline for 403	2014 August	26	4	81
Speedometer cable	2016 May	23	3	94
Speedometer inaccurate	2011 May	22	1	49
General				
'70 and '70 1/2 differences	2010 August	26	2	42
'78 Firebird rebuild	2016 February	23	1	92
Car shaking	2011 August	22	1	52
Collector car registration	2008 August	22	2	22
Firebird show cars	2012 May	27		61
Firebird value	2008 January	21	2	13
Locked out	2016 August	25	2	97
Multiple problems	2013 November	23	2	73
Original manuals	2011 May	23	2	50
Performance increase	2011 May	23	4	50
Power in '86	2012 February	26	1	57
Rattling noise	2011 May	27	3	51
Restoration for '79	2009 February	22	2	33
Trans Am value	2008 May	22	2	17
Value of '68 Firebird	2009 May	21	2	27
Vibration on 4th gen Firebirds	2013 August	27		72
Winter storage tips	2016 February	26		93
Interior				
Color combinations	2008 May	22	1	17
Dash repair	2010 May	23	2	38
Dashpad replacement	2008 November	22	1	21
Driver door decals	2008 August	26	1	20
Door panel crack	2014 May	23	1	78
Door panel parts	2008 August	22	1	19
Floor mats	2013 August	23	3	70
Headliner installation	2009 August	26	1	3

SUBJECT/ ARTICLE	ORIGINAL PUBLICATION		PAGE NUMBER	
	ISSUE	PAGE	Q & A	THIS ISSUE
Headliner replacement	2016 May	23	2	94
Key broke in ignition	2015 May	26	3	87
Shoulder belt clips	2009 May	26	3	29
Tilt column swap	2008 January	21	1	13
Windshield fogging up	2014 August	23	3	80
Numbers/Identification				
Build sheet	2009 May	22	1	28
Engine code for '77	2008 November	26	1	22
Engine number plate	2010 August	23	2	41
Engine number plate meaning	2010 November	26	5	45
Number of '84 anniversary cars built	2015 February	23	1	84
Numbers matching	2008 August	21	1	18
Paint stripping	2010 August	23	4	41
VIN decoding 4th generation	2012 August	27		63
Oil/Lubrication				
Oil amount in 403 engine	2009 August	27	2	34
Oil filter brand	2012 November	23	12	65
Oil pump	2013 February	26	3	66
Oil type to use	2014 August	26	1	81
Rear end fluid	2017 February	24	1	100
Regular or synthetic oil	2015 February	23	3	84
Suspension/Handling				
323 Auburn gear	2014 November	26	2	83
Best suspension setup on '70 T/As	2017 February	24	3	100
Coil spring replacement	2011 May	27	2	51
Rear end gears	2015 August	23	3	88
Rear end swap	2010 November	26	3	45
Rear end whine	2017 May	26	1	103
Sway bar end links	2014 February	23	2	76
Tires/Wheels				
High performance tires	2012 November	26	1	65
Rim size	2014 May	26	6	79
Tire types	2010 November	26	4	45
Torque setting for wheels	2011 February	22	2	47
Wheel locks for '82 to '83	2009 August	27	1	34

SUBJECT/ <u>ARTICLE</u>	ORIGINAL PUBLICATION		PAGE NUMBER	
	<u>ISSUE</u>	<u>PAGE</u>	<u>Q & A</u>	<u>THIS ISSUE</u>
Wheel restoration	2012 August	27		63
Wheel types	2012 May	26	3	60
Transmission/Clutch/Drive Train				
2nd gear start switch	2011 November	22	1	54
700R4 shifter not fitting	2014 May	26	5	79
700R4 transmission	2013 August	26	5	71
B&M shifter installation	2008 November	22	2	21
Clutch slipping	2013 August	26	6	71
Dip stick pushing up	2015 May	26	1	87
Hurst shifter usage	2015 February	26	2	85
No reverse	2013 November	26	5	74
NOS shifters	2017 May	25	1	102
TH350 and TH400 differences	2010 August	26	1	42
TH350 to 700R4 swap	2014 February	26	5	77
Transmission swapping	2010 May	23	1	38

