



NATIONAL FIREBIRD and TRANS AM CLUB

TECHNICAL SECTIONS Volume III

Reprints from the 2008 thru 2017 NFTAC *EAGLE*

AVAILABLE IN CD AND PRINTED FORMATS

Volume I and Volume II covering publications also available from the NFTAC

PUBLISHED BY THE NFTAC
5433 N. ASHLAND AVE., CHICAGO, IL 60640 U.S.A.
Phone: 773-769-7166
FAX: 773-769-3240
email: info@firebirdtaclub.com
web site: firebirdtaclub.com or www.firebirdclub.net

NFTAC TECHNICAL SECTIONS VOLUME III

<u>PUBLICATION</u>	<u>PAGE</u>
2008 January	13
2008 May	16
2008 August	18
2008 November	21
2009 February	24
2009 May	27
2009 August	27
2010 January	35
2010 May	38
2010 August	41
2010 November	44
2011 February	47
2011 May	49
2011 August	52
2011 November	54
2012 February	56
2012 May	59
2012 August	62
2012 November	64
2013 February	66
2013 May	68
2013 August	70
2013 November	73
2014 February	76
2014 May	74
2014 August	80
2014 November	82
2015 February	84
2015 May	86
2015 August	88
2015 November	90
2016 February	92
2016 May	90
2016 August	96
2016 November	98
2017 February	100
2017 May	102
NFTAC Store Order Form	104
NFTAC Membership Application	105

NOTE: Please note the ads that may appear here are reproduced as they originally appeared in that issue and therefore may be several years old and are not to be relied on for prices or information.

Nothing may be reproduced in whole or in part without the express written consent of the publisher. The views of contributing writers are their own and not necessarily the views of the NFTAC. Readers are warned in following any advice given and no liability either express or implied is assumed by the advice or opinions given by individual contributors or the NFTAC.

ARTICLE INDEX

Publication references in which NFTAC publication the article originally appeared and the year; the page number it was on and if a Question and Answer (Q & A), its position on the page and page number in this issue.

SUBJECT/ <u>ARTICLE</u>	ORIGINAL PUBLICATION		PAGE NUMBER	
	<u>ISSUE</u>	<u>PAGE</u>	<u>Q & A</u>	<u>THIS ISSUE</u>
Brakes				
Brakes pulsing	2016 May	23	1	94
Caliper sizes	2008 August	21	3	18
Disc brake conversion	2009 February	26	2	25
Rear brakes not working	2016 August	24	1	96
Rear drum to disc conversion	2015 August	26		89
Carburetion/Fuel System				
305 to 350 carburetor	2014 February	26	1	77
Car shutting off	2013 May	26	2	68
Carb problems	2009 May	26	4	33
Carb size	2011 November	23	3	54
Carburetor throttle	2008 November	26	2	22
Carburetor troubleshooting	2010 January	27	1	37
Edelbrock carb	2009 August	21	1	31
Edelbrock performer package	2014 November	26	1	83
Fuel pump and no gas	2012 February	23	2	56
Fuel pump problems	2013 August	23	2	70
Fuel pump relay	2016 November	24	2	98
Fuel pump relay	2016 November	25	1	99
Gas incorrect	2013 August	26	3	71
No throttle response	2009 May	26	2	29
T.P. I. throttle	2013 November	26	4	74
Cooling/Heating Systems				
A/C evaporate condensate line	2010 January	26	2	36
A/C and heat duct pipes	2015 May	26	4	87
Coolant flow sensor	2012 May	26	5	60
Coolant hose leak	2010 November	26	1	45
Coolant lights	2012 May	26	4	60
Heater control vacuum	2009 August	26	2	33
Heater core replacement	2011 February	22	1	47
Heater core replacing	2011 November	22	2	54
Heater not working	2014 May	26	3	79
Overheating	2013 November	27		75

SUBJECT/ <u>ARTICLE</u>	ORIGINAL PUBLICATION		PAGE NUMBER	
	<u>ISSUE</u>	<u>PAGE</u>	<u>Q & A</u>	<u>THIS ISSUE</u>
Overheating caused by fan	2016 August	25	1	97
Electrical				
Battery runs down	2008 August	21	4	18
Blinkers not working	2015 August	23	2	88
Chip question	2017 February	24	4	100
Computer out	2013 August	26	1	71
Delco alternator number	2017 May	25	2	102
Electric schematic diagram	2008 May	21	1	16
Electrical problems	2008 November	27	1	22
Exterior lights	2010 November	23	1	44
Fan switch	2013 May	26	3	68
Fuse box power	2010 August	26	3	42
HID headlight installation	2012 May	26	1	60
Not starting	2015 August	23	1	88
Vats system	2016 November	24	3	98
Wiring harness swap	2010 August	23	3	41
Wiring harness source	2012 May	23	1	59
Wiring harness swap	2010 August	23	3	41
Emission Controls				
EGR flow code	2012 August	26	2	62
Emission conversion	2012 August	26	3	62
Filler cap tightness	2012 May	26	2	60
Mass airflow sensor	2010 August	23	1	41
Mass airflow sensor code	2010 November	26	6	45
Mass airflow sensor removal	2012 February	26	3	57
Mass airflow sensor replacement	2014 August	23	2	80
Oxygen sensor	2012 February	26	6	57
Oxygen sensor code	2012 August	26	1	62
Engine/Mechanical				
'81 T/A engines	2012 February	26	2	57
400 version in '78 Formula	2011 May	27	1	51
403 rebuild	2015 February	26	3	85
Belt noises	2009 February	26	1	25
Block and head castings	2016 February	23	2	92
Block value	2011 February	22	2	47
Car not starting	2013 November	26	2	74

SUBJECT/ ARTICLE	ORIGINAL PUBLICATION		PAGE NUMBER	
	ISSUE	PAGE	Q & A	THIS ISSUE
Check engine light	2010 May	26	1	39
Compression	2013 May	26	1	68
Cruise control operational	2010 January	27	2	37
Engine block seal	2011 November	23	4	55
Engine knock	2015 May	26	1	87
Engine surge	2015 February	26	1	85
Engine swap in '83 Firebird	2014 February	23	3	76
Engine will not start	2013 February	26	1	66
Gasket set	2017 May	25	3	102
High torque starter	2013 May	27	2	69
Horsepower adding	2011 November	22	3	54
Horsepower increase	2015 May	23	3	86
Horsepower ratings	2011 May	23	6	50
Idle speed	2010 January	26	1	36
Ignition timing	2015 May	23	1	86
Injector replacement	2012 November	23	2	64
LT1 rebuild	2014 August	26	3	81
Misfire	2012 May	23	2	59
More power from 403	2014 February	26	4	77
Optispark distributor	2017 February	24	2	100
Original engine in '67 Firebird	2011 November	23	1	55
PCM flashing	2012 November	23	1	64
Peak performance in '78 WS6	2014 February	26	3	77
Ram air V engine	2012 February	27		58
Running rough	2013 November	23	1	73
Service engine light	2013 November	26	1	74
Starting problem	2016 November	24	1	98
Timing	2015 May	23	1	86
Timing setting	2016 February	26		93
Tuning new engine	2010 January	23	2	35
Turbo, carb, ignition	2013 August	26	2	71
Vortec heads	2014 May	26	4	79
Vortec supercharger	2013 August	27		62
WS package for 1984	2014 November	23	1	82
WS6 performance options	2012 February	26	4	57
Exhaust				
Exhaust sound	2014 August	26	2	81
Header wrap	2014 May	23	2	78

SUBJECT/ ARTICLE	ORIGINAL PUBLICATION		PAGE NUMBER	
	ISSUE	PAGE	Q & A	THIS ISSUE
Headers	2013 February	26	2	66
Headers in '87 Firebird	2014 May	26	1	79
RA III exhaust	2013 November	26	3	74
Straight pipe exhaust	2014 May	26	2	79
Exterior/Body				
'96 and '97 headlight doors	2012 February	27		57
Aero kit	2013 November	23	2	73
Bird decal adhesive	2014 May	23	3	78
Body shell	2008 January	22	1	14
Bumper emblems	2011 May	23	3	50
Car cover	2010 November	26	2	45
Convertible top/seals	2011 May	23	1	50
Doors for '98 Firebird	2016 May	26	1	95
Exterior trim colors	2009 February	22	1	24
Fender replacement	2009 May	21	1	27
Headlights flipping open	2012 February	23	1	56
Headlights manually opening	2008 May	22	3	17
Headlight height adjustment	2009 August	27	3	34
Headlight not opening	2015 May	23	2	86
Hood decal	2012 February	26	5	57
Hood scoop function	2008 May	21	2	16
Items to get great paint	2015 November	26		91
Key replacement	2008 August	21	2	18
Nose and grille swap	2008 August	26	2	20
Original color and value	2009 May	22	2	28
Original chrome shine	2010 January	23	1	35
Paint bubbles	2015 August	26		89
Paint bubbling	2014 August	23	1	80
Paint code	2013 August	23	1	70
Personal preferences	2014 May	26	7	79
Pop up headlights	2008 November	26	3	22
Primers, all about	2010 May	27		40
Primer factory colors	2010 August	27		43
Rear quarter repair	2013 August	26	4	71
Scoop seal	2009 May	27	1	30
Sequential tail lights	2013 February	27		67
Spoiler cracking	2014 February	23	1	76
Striping source	2011 November	23	2	55

SUBJECT/ ARTICLE	ORIGINAL PUBLICATION		PAGE NUMBER	
	ISSUE	PAGE	Q & A	THIS ISSUE
T-top conversion	2012 May	26	6	60
T-top type	2011 May	27	1	51
Windshield cowl rust holes	2008 November	22	3	21
Winter car wash	2011 February	27		48
WS6 markings	2017 February	25	1	101
Gauges				
Redline for 403	2014 August	26	4	81
Speedometer cable	2016 May	23	3	94
Speedometer inaccurate	2011 May	22	1	49
General				
'70 and '70 1/2 differences	2010 August	26	2	42
'78 Firebird rebuild	2016 February	23	1	92
Car shaking	2011 August	22	1	52
Collector car registration	2008 August	22	2	22
Firebird show cars	2012 May	27		61
Firebird value	2008 January	21	2	13
Locked out	2016 August	25	2	97
Multiple problems	2013 November	23	2	73
Original manuals	2011 May	23	2	50
Performance increase	2011 May	23	4	50
Power in '86	2012 February	26	1	57
Rattling noise	2011 May	27	3	51
Restoration for '79	2009 February	22	2	33
Trans Am value	2008 May	22	2	17
Value of '68 Firebird	2009 May	21	2	27
Vibration on 4th gen Firebirds	2013 August	27		72
Winter storage tips	2016 February	26		93
Interior				
Color combinations	2008 May	22	1	17
Dash repair	2010 May	23	2	38
Dashpad replacement	2008 November	22	1	21
Driver door decals	2008 August	26	1	20
Door panel crack	2014 May	23	1	78
Door panel parts	2008 August	22	1	19
Floor mats	2013 August	23	3	70
Headliner installation	2009 August	26	1	3

SUBJECT/ ARTICLE	ORIGINAL PUBLICATION		PAGE NUMBER	
	ISSUE	PAGE	Q & A	THIS ISSUE
Headliner replacement	2016 May	23	2	94
Key broke in ignition	2015 May	26	3	87
Shoulder belt clips	2009 May	26	3	29
Tilt column swap	2008 January	21	1	13
Windshield fogging up	2014 August	23	3	80
Numbers/Identification				
Build sheet	2009 May	22	1	28
Engine code for '77	2008 November	26	1	22
Engine number plate	2010 August	23	2	41
Engine number plate meaning	2010 November	26	5	45
Number of '84 anniversary cars built	2015 February	23	1	84
Numbers matching	2008 August	21	1	18
Paint stripping	2010 August	23	4	41
VIN decoding 4th generation	2012 August	27		63
Oil/Lubrication				
Oil amount in 403 engine	2009 August	27	2	34
Oil filter brand	2012 November	23	12	65
Oil pump	2013 February	26	3	66
Oil type to use	2014 August	26	1	81
Rear end fluid	2017 February	24	1	100
Regular or synthetic oil	2015 February	23	3	84
Suspension/Handling				
323 Auburn gear	2014 November	26	2	83
Best suspension setup on '70 T/As	2017 February	24	3	100
Coil spring replacement	2011 May	27	2	51
Rear end gears	2015 August	23	3	88
Rear end swap	2010 November	26	3	45
Rear end whine	2017 May	26	1	103
Sway bar end links	2014 February	23	2	76
Tires/Wheels				
High performance tires	2012 November	26	1	65
Rim size	2014 May	26	6	79
Tire types	2010 November	26	4	45
Torque setting for wheels	2011 February	22	2	47
Wheel locks for '82 to '83	2009 August	27	1	34

SUBJECT/ <u>ARTICLE</u>	ORIGINAL PUBLICATION		PAGE NUMBER	
	<u>ISSUE</u>	<u>PAGE</u>	<u>Q & A</u>	<u>THIS ISSUE</u>
Wheel restoration	2012 August	27		63
Wheel types	2012 May	26	3	60
Transmission/Clutch/Drive Train				
2nd gear start switch	2011 November	22	1	54
700R4 shifter not fitting	2014 May	26	5	79
700R4 transmission	2013 August	26	5	71
B&M shifter installation	2008 November	22	2	21
Clutch slipping	2013 August	26	6	71
Dip stick pushing up	2015 May	26	1	87
Hurst shifter usage	2015 February	26	2	85
No reverse	2013 November	26	5	74
NOS shifters	2017 May	25	1	102
TH350 and TH400 differences	2010 August	26	1	42
TH350 to 700R4 swap	2014 February	26	5	77
Transmission swapping	2010 May	23	1	38

